

MAC Services, LLC

Environmental Specialist

November 11, 2020


Town of Somerset School Department
580 Whetstone Hill Road
Somerset, MA 02726
Attention: Carlos Campos

Re: Clarification of follow up mold inspection report for the Middle School located at 1141 Brayton Avenue in Somerset, MA.

I wanted to clarify the visual inspection results description discussed in the original Follow Up Inspection letter dated October 30, 2020, as my understanding is there may still be a lack of fully comprehending what was observed. After visually inspecting every room in the building, opening cabinets, looking under desks, looking at walls, furnishings bookcases and desks, there was a total of Ten (10) isolated areas found in the entire building, all less than 1 to 2 Square feet in surface area, that were found and cleaned. These were not areas of new mold growth rather very small areas that were just missed originally. Again, examples are the corner of a shelf inside a cabinet, underside of a chair, underside of a metal desk. These areas, again, were not new mold growth but were very isolated small areas that were then cleaned. The overall results of both the air sampling and visual inspection were excellent and meet every criteria of industry guidelines for occupancy.

I hope this clears up any misunderstanding of the original report.

Regards,



Joseph Cooney
MAC Services, LLC