

APPENDIX A

Direct Reading Environmental Measurements from August 18th, 2020

Direct Reading Environmental Measurements – Obtained by two different Technicians on August 18th, 2020 between 1221 and 1354 hours from within Chace Street Elementary School.

LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Room 11	1	1221	57	77	0	0	0	20.9	0
Room 15	1	1224	58	77	0	0	0	20.9	0
Room 9	1	1226	57	78	0	0	0	20.9	0
Room 12	1	1229	57	79	0	0	0	20.9	0
Room 7	1	1231	58	79	0	0	0	20.9	0
Band	1	1234	58	79	0	0	0	20.9	0
Room 6	1	1237	58	79	0	0	0	20.9	0
Cafeteria	1	1239	59	79	0	0	0	20.9	0
Kitchen	1	1242	59	79	0	0	0	20.9	0
Outdoors	1	1344	60	79	0	0	0	20.9	0
Room 24 Preschool	1	1230	-	-	0	0	0	20.9	0
Room 25 Preschool	1	1232	-	-	0	0	0	20.9	0
Room 5 Preschool	1	1234	-	-	0	0	0	20.9	0
Room 2 Preschool	1	1236	-	-	0	0	0	20.9	0
Room 1 Art and Music	1	1238	-	-	0	0	0	20.9	0
Teachers Dining	1	1240	-	-	0	0	0	20.9	0
Room 23 Speech	1	1242	-	-	0	0	0	20.9	0
Library and Media Center	1	1244	-	-	0	0	0	20.9	0
Room 21 SPED	1	1246	-	-	0	0	0	20.9	0.1
Room 19 Grade 1	1	1248	-	-	0	0	0	20.9	0
Gymnasium	1	1250	-	-	0	0	0	20.9	0.1
Room 16 Grade 1	1	1252	-	-	0	0	0	20.9	0
Outside	1	1353	-	-	0	0	0	20.9	0
Room 11	2	1245	-	-	0	0	0	20.9	0
Room 15	2	1247	-	-	0	0	0	20.9	0
Room 9	2	1251	-	-	0	0	0	20.9	0
Room 12	2	1253	-	-	0	0	0	20.9	0

Room 7	2	1255	-	-	0	0	0	20.9	0
Band	2	1257	-	-	0	0	1	20.9	0
Room 6	2	1259	-	-	0	0	0	20.9	0
Cafeteria	2	1302	-	-	0	0	0	20.9	0
Kitchen	2	1305	-	-	0	0	0	20.9	0
Outdoors	2	1346	-	-	0	0	0	20.9	0
Room 24 Preschool	2	1300	-	-	0	0	0	20.9	0
Room 25 Preschool	2	1302	-	-	0	0	0	20.9	0
Room 5 Preschool	2	1304	-	-	0	0	0	20.9	0
Room 2 Preschool	2	1306	-	-	0	0	0	20.9	0
Room 1 Art and Music	2	1308	-	-	0	0	0	20.9	0
Teachers Dining	2	1310	-	-	0	0	0	20.9	0
Room 23 Speech	2	1312	-	-	0	0	0	20.9	0
Library and Media Center	2	1314	-	-	0	0	0	20.9	0
Room 21 SPED	2	1316	-	-	0	0	0	20.9	0
Room 19 Grade 1	2	1318	-	-	0	0	0	20.9	0.1
Gymnasium	2	1320	-	-	0	0	0	20.9	0
Room 16 Grade 1	2	1322	-	-	0	0	0	20.9	0
Outside	2	1354	-	-	0	0	0	20.9	0
Room 11	3	1310	-	-	0	0	0	20.9	0
Room 15	3	1314	-	-	0	0	0	20.9	0
Room 12	3	1316	-	-	0	0	0	20.9	0
Room 7	3	1319	-	-	0	0	0	20.9	0
Band	3	1321	-	-	0	0	0	20.9	0
Room 6	3	1324	-	-	0	0	0	20.9	1
Cafeteria	3	1330	-	-	0	0	0	20.9	0
Kitchen	3	1333	-	-	0	0	0	20.9	0
Outdoors	3	1341	-	-	0	0	0	20.9	0
Room 24 Preschool	3	1318	54	79	0	0	0	20.9	0
Room 25 Preschool	3	1330	54	79	0	0	0	20.9	0
Room 5 Preschool	3	1332	55	79	0	0	0	20.9	0
Room 2 Preschool	3	1334	55	79	0	0	0	20.9	0
Room 1 Art and Music	3	1336	56	79	0	0	0	20.9	0
Teachers Dining	3	1338	56	79	0	0	0	20.9	0
Room 23 Speech	3	1340	56	79	0	0	0	20.9	0

Library and Media Center	3	1342	57	79	0	0	0	20.9	0
Room 21 SPED	3	1344	58	79	0	0	0	20.9	0
Room 19 Grade 1	3	1346	58	79	0	0	0	20.9	0
Gymnasium	3	1348	58	79	0	0	0	20.9	0
Room 16 Grade 1	3	1350	57	79	0	0	0	20.9	0
Outside	3	1353	-	-	0	0	0	20.9	0

APPENDIX B

Mold Laboratory Analytical Results