

## **APPENDIX A**

### **Direct Reading Environmental Measurements from August 18<sup>th</sup>, 2020**

**Direct Reading Environmental Measurements – Obtained by two different Environmental Technicians on August 18<sup>th</sup>, 2020 between 0907 and 1115 hours from within the South Elementary School.**

LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Room 13	1	0907	61	73	0	0	0	20.9	0
Room 12	1	0910	62	73	0	0	0	20.9	0
Sanitary	1	0914	63	75	0	0	0	20.9	0
4-5 Restroom	1	0916	62	75	0	0	0	20.9	0
Room 10	1	0919	63	75	0	0	0	20.9	0
Custodial	1	0922	62	75	0	0	0	20.9	0
Clubhouse	1	0924	63	75	0	0	0	20.9	0
Room 1	1	0926	63	75	0	0	0	20.9	0
Girls Restroom Gr 3	1	0928	63	75	0	0	0	20.9	0
Main Office	1	0932	64	75	0	0	0	20.9	0
Nurse Room	1	0936	64	75	0	0	0	20.9	0
Room 5	1	0902	-	-	0	0	2	20.9	0
Room 6	1	0906	-	-	0	0	2	20.9	0
Room 8	1	0908	-	-	0	0	1	20.9	0
Room 3	1	0910	-	-	0	0	2	20.9	0
Custodial Space	1	0912	-	-	0	0	2	20.9	0
Faculty	1	0914	-	-	0	0	2	20.9	0
Maintenance Mr. Greene	1	0916	-	-	0	0	2	20.9	0
Cafeteria/Gym	1	0918	-	-	0	0	2	20.9	0
Book Room	1	0920	-	-	0	0	2	20.9	0
Kitchen	1	0923	-	-	0	0	2	20.9	0
Gym Storage Room	1	0925	-	-	0	0	2	20.9	0
Library Smaller Building	1	1053	62	79	0	0	2	20.9	0
Outdoors	1	1110	-	-	0	0	0	20.9	0
Room 13	2	0943	-	-	0	0	0	20.9	0

Room 12	2	0946	-	-	0	0	0	20.9	0
Sanitary/Bathroom	2	0950	-	-	0	0	0	20.9	0
4-5 Restroom	2	0954	-	-	0	0	0	20.9	0
Room 10	2	0956	-	-	0	0	0	20.9	0
Custodial	2	0958	-	-	0	0	0	20.9	0
Room 1	2	1000	-	-	0	0	0	20.9	0
Clubhouse	2	1002	-	-	0	0	0	20.9	0
Girls Restroom Gr 3	2	1004	-	-	0	0	0	20.9	0
Main Office	2	1006	-	-	0	0	0	20.9	0
Nurse Room	2	1008	-	-	0	0	0	20.9	0
Room 5	2	0931	63	72	0	0	2	20.9	0
Room 6	2	0934	62	73	0	0	2	20.9	0
Room 8	2	0937	62	75	0	0	2	20.9	0
Room 3	2	0939	64	75	0	0	2	20.9	0
Custodial Space	2	0941	61	74	0	0	2	20.9	0
Faculty	2	0943	61	74	0	0	2	20.9	0
Maintenance Mr. Greene	2	0945	61	75	0	0	2	20.9	0
Cafeteria/Gym	2	0948	62	75	0	0	2	20.9	0
Book Room	2	0950	63	75	0	0	2	20.9	0
Kitchen	2	0954	64	73	0	0	2	20.9	0
Gym Storage Room	2	0958	64	75	0	0	2	20.9	0
Library Smaller Building	2	1100	-	-	0	0	0	20.9	0
Outdoors	2	1112	-	-	0	0	0	20.9	0
Room 13	3	1011	-	-	0	0	0	20.9	0
Room 12	3	1013	-	-	0	0	0	20.9	0
Sanitary/Restroom	3	1016	-	-	0	0	0	20.9	0
4-5 Restroom	3	1018	-	-	0	0	0	20.9	0
Custodial	3	1022	-	-	0	0	0	20.9	0
Room 10	3	1025	-	-	0	0	0	20.9	0
Room 1	3	1029	-	-	0	0	0	20.9	0
Clubhouse	3	1032	-	-	0	0	0	20.9	0
Girls Restroom Gr 3	3	1035	-	-	0	0	0	20.9	0

Main Office	3	1040	-	-	0	0	2	20.9	0
Adjustment Counselor	3	1037	-	-	0	0	2	20.9	0
Room 5	3	1005	-	-	0	0	2	20.9	0
Room 6	3	1008	-	-	0	0	2	20.9	0
Room 8	3	1010	-	-	0	0		20.9	0
Room 3	3	1012	-	-	0	0	2	20.9	0
Custodial Space	3	1015	-	-	0	0	2	20.9	0
Faculty	3	1018	-	-	0	0	2	20.9	0
Maintenance Mr. Greene	3	1020	-	-	0	0	2	20.9	0
Cafeteria/Gym	3	1022	-	-	0	0	2	20.9	0
Book Room	3	1025	-	-	0	0	0	20.9	0
Kitchen	3	1027	-	-	0	0	0	20.9	0
Gym Storage Room	3	1030	-	-	0	0	0	20.9	0
Library Smaller Building	3	1103	-	-	0	0	0	20.9	0
Outdoors	3	1115	-	-	0	0	0	20.9	0

## **APPENDIX B**

### **Mold Laboratory Analytical Results**