

APPENDIX A

Direct Reading Environmental Measurements from August 4th, 2021

Direct Reading Environmental Measurements – Obtained by Technician on August 4th, 2021 between 0826 and 1110 hours from within Somerset Middle School.

LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Room 37	1	0826	-	-	0	0	0	20.9	0
Room 36	1	-	-	-	0	0	0	20.9	0
Room 34	1	-	-	-	0	0	0	20.9	0
Cafeteria	1	-	-	-	0	0	0	20.9	0
Room 32	1	-	-	-	0	0	0	20.9	0
Room 30	1	-	-	-	0	0	0	20.9	0
Room 16	1	-	-	-	0	0	0	20.9	0
Room 44	1	-	-	-	0	0	0	20.9	0
Practice 'A' Room	1	-	-	-	0	0	0	20.9	0
Practice 'B' Room	1	-	-	-	0	0	0	20.9	0
Room 45	1	-	-	-	0	0	0	20.9	0
Room 46	1	-	-	-	0	0	0	20.9	0
ART Area	1	-	-	-	0	0	0	20.9	0
Room 48	1	-	-	-	0	0	0	20.9	0
Teachers Lounge (next to ART)	1	-	-	-	0	0	0	20.9	0
Room 51	1	-	-	-	0	0	0	20.9	0
Room 53	1	-	-	-	0	0	0	20.9	0
Room 54	1	-	-	-	0	0	0	20.9	0
Room 56	1	-	-	-	0	0	0	20.9	0
Room 58	1	-	-	-	0	0	0	20.9	0
Room 62	1	-	-	-	0	0	0	20.9	0
Room 60	1	-	-	-	0	0	0	20.9	0
Front Lobby	1	-	-	-	0	0	0	20.9	0
GYM	1	-	-	-	0	0	0	20.9	0
Boys Locker Room Office	1	-	-	-	0	0	0	20.9	0
Girls Locker Room Office	1	-	-	-	0	0	0	20.9	0
Lobby in back or GYM	1	-	-	-	0	0	0	20.9	0
Outdoors at front	1	-	-	-	0	0	0	20.9	0

Main Office	1	-	-	-	0	0	0	20.9	0
Room 6	1	-	-	-	0	0	0	20.9	0
Room 54	1	-	-	-	0	0	0	20.9	0
Room 2	1	-	-	-	0	0	0	20.9	0
Graphic Arts	1	-	-	-	0	0	0	20.9	0
Wood Shop	1	-	-	-	0	0	0	20.9	0
Auditorium Stage	1	-	-	-	0	0	0	20.9	0
Music Room	1	-	-	-	0	0	0	20.9	0
Teachers Lounge off of Kitchen	1	-	-	-	0	0	0	20.9	0
Kitchen	1	-	-	-	0	0	0	20.9	0
Nurse Office	1	-	-	-	0	0	0	20.9	0
Room 12	1	-	-	-	0	0	0	20.9	0
Guidance Office	1	-	-	-	0	0	0	20.9	0
Room 13A	1	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Room 37	2	-	-	-	0	0	0	20.9	0
Room 36	2	-	-	-	0	0	0	21.1	0
Room 34	2	-	-	-	0	0	0	21.1	0
Cafeteria	2	-	-	-	0	0	0	20.9	0
Room 32	2	-	-	-	0	0	0	20.9	0
Room 30	2	-	-	-	0	0	0	20.9	0
Room 16	2	-	-	-	0	0	0	21.1	0
Room 44	2	-	-	-	0	0	0	21.1	0
Practice 'A' Room	2	-	-	-	0	0	0	21.1	0
Practice 'B' Room	2	-	-	-	0	0	0	21.1	0
Room 45	2	-	-	-	0	0	0	21.1	0
Room 46	2	-	-	-	0	0	0	21.1	0
ART Area	2	-	-	-	0	0	0	21.1	0
Room 48	2	-	-	-	0	0	0	21.1	0
Teachers Lounge (next to ART)	2	-	-	-	0	0	0	21.1	0
Room 51	2	-	-	-	0	0	0	21.1	0
Room 53	2	-	-	-	0	0	0	21.1	0

Room 54	2	-	-	-	0	0	0	21.1	0
Room 56	2	-	-	-	0	0	0	20.9	0
Room 58	2	-	-	-	0	0	0	20.9	0
Room 62	2	-	-	-	0	0	0	20.9	0
Room 60	2	-	-	-	0	0	0	20.9	0
Front Lobby	2	-	-	-	0	0	0	20.9	0
GYM	2	-	-	-	0	0	0	20.9	0
Boys Locker Room Office	2	-	-	-	0	0	0	20.9	0
Girls Locker Room Office	2	-	-	-	0	0	0	20.9	0
Lobby in back or GYM	2	-	-	-	0	0	0	20.9	0
Outdoors at front	2	-	-	-	0	0	0	20.9	0
Main Office	2	-	-	-	0	0	0	20.9	0
Room 6	2	-	-	-	0	0	0	20.9	0
Room 54	2	-	-	-	0	0	0	20.9	0
Room 2	2	-	-	-	0	0	0	20.9	0
Graphic Arts	2	-	-	-	0	0	0	20.9	0
Wood Shop	2	-	-	-	0	0	0	20.9	0
Auditorium Stage	2	-	-	-	0	0	0	20.9	0
Music Room	2	-	-	-	0	0	0	20.9	0
Teachers Lounge off of Kitchen	2	-	-	-	0	0	0	20.9	0
Kitchen	2	-	-	-	0	0	0	20.9	0
Nurse Office	2	-	-	-	0	0	0	20.9	0
Room 12	2	-	-	-	0	0	0	20.9	0
Guidance Office	2	-	-	-	0	0	0	20.9	0
Room 13A	2	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	-	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT		-	<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Room 37	3	-	-	-	0	0	0	21.1	0
Room 36	3	-	-	-	0	0	0	21.1	0
Room 34	3	-	-	-	0	0	0	20.9	0
Cafeteria	3	-	-	-	0	0	0	20.9	0
Room 32	3	-	-	-	0	0	0	20.9	0

Room 30	3	-	-	-	0	0	0	20.9	0
Room 16	3	-	-	-	0	0	0	20.9	0
Room 44	3	-	-	-	0	0	0	20.9	0
Practice 'A' Room	3	-	-	-	0	0	0	20.9	0
Practice 'B' Room	3	-	-	-	0	0	0	20.9	0
Room 45	3	-	-	-	0	0	0	20.9	0
Room 46	3	-	-	-	0	0	0	20.9	0
ART Area	3	-	-	-	0	0	0	20.9	0
Room 48	3	-	-	-	0	0	0	20.9	0
Teachers Lounge (next to ART)	3	-	-	-	0	0	0	20.9	0
Room 51	3	-	-	-	0	0	0	20.9	0
Room 53	3	-	-	-	0	0	0	20.9	0
Room 54	3	-	-	-	0	0	0	20.9	0
Room 56	3	-	-	-	0	0	0	20.9	0
Room 58	3	-	-	-	0	0	0	20.9	0
Room 62	3	-	-	-	0	0	0	20.9	0
Room 60	3	-	-	-	0	0	0	20.9	0
Front Lobby	3	-	-	-	0	0	0	20.9	0
GYM	3	-	-	-	0	0	0	20.9	0
Boys Locker Room Office	3	-	-	-	0	0	0	20.9	0
Girls Locker Room Office	3	-	-	-	0	0	0	20.9	0
Lobby in back or GYM	3	-	-	-	0	0	0	20.9	0
Outdoors at front	3	-	-	-	0	0	0	20.9	0
Main Office	3	-	-	-	0	0	0	20.9	0
Room 6	3	-	-	-	0	0	0	20.9	0
Room 54	3	-	-	-	0	0	0	20.9	0
Room 2	3	-	-	-	0	0	0	20.9	0
Graphic Arts	3	-	-	-	0	0	0	20.9	0
Wood Shop	3	-	-	-	0	0	0	20.9	0
Auditorium Stage	3	-	-	-	0	0	0	20.9	0
Music Room	3	-	-	-	0	0	0	20.9	0
Teachers Lounge off of Kitchen	3	-	-	-	0	0	0	20.9	0
Kitchen	3	-	-	-	0	0	0	20.9	0
Nurse Office	3	-	-	-	0	0	0	20.9	0

Room 12	3	-	-	-	0	0	0	20.9	0
Guidance Office	3	-	-	-	0	0	0	20.9	0
Room 13A	3	1110	-	-	0	0	0	20.9	0

APPENDIX B

Mold Laboratory Analytical Results