

APPENDIX A

Direct Reading Environmental Measurements from August 4th, 2021

Direct Reading Environmental Measurements – Obtained by a technician on August 4th, 2021 between 1207 and 1355 hours from within the North Elementary School.

LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Top level class rooms	1	1207	-	-	0	0	0	20.9	0
Pre-K, East side(1 st floor)	1	-	-	-	0	0	0	20.9	0
Conference room next to Pre-K	1	-	-	-	0	0	0	20.9	0
Open Area “D” North Side	1	-	-	-	0	0	0	20.9	0
Open Area “E” East Side	1	-	-	-	0	0	0	20.9	0
Open Area “F” West Side	1	-	-	-	0	0	0	20.9	0
Open Area “C” East Side	1	-	-	-	0	0	0	20.9	0
Open Area “G” West Side	1	-	-	-	0	0	0	20.9	0
Open Area “H” East Side	1	-	-	-	0	0	0	20.9	0
Library Center	1	-	-	-	0	0	0	20.9	0
Book storage room	1	-	-	-	0	0	0	20.9	0
Teachers Lounge off Library	1	-	-	-	0	0	0	20.9	0
Main Office	1	-	-	-	0	0	0	20.9	0
Open Area “K” West Side	1	-	-	-	0	0	0	20.9	0
Outdoors at South side	1	-	-	-	0	0	0	20.9	0
Room 9	1	-	-	-	0	0	0	20.9	0
Room 8	1	-	-	-	0	0	0	20.9	0
Room 6	1	-	-	-	0	0	0	20.9	0
Custodian closet	1	-	-	-	0	0	0	20.9	0
Nurse Office	1	-	-	-	0	0	0	20.9	0
“I” Area	1	-	-	-	0	0	0	20.9	0
Student Services Conference Room	1	-	-	-	0	0	0	20.9	0
Basement Pre-K area hallway	1	-	-	-	0	0	0	20.9	0
Basement Pre-K Copy area	1	-	-	-	0	0	0	20.9	0

Kitchen next to ovens	1	-	-	-	0	0	0	20.9	0
Kitchen Storage room	1	-	-	-	0	0	0	20.9	0
Kitchen Laundry area	1	-	-	-	0	0	0	20.9	0
Cafeteria, East side	1	-	-	-	0	0	0	20.9	0
Dishwashing room	1	-	-	-	0	0	0	20.9	0
E12 Stairwell	1	-	-	-	0	0	0	20.9	0
Mechanical room (EMR)	1	-	-	-	0	0	0	20.9	0
Maintenance area, East side	1	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Top level class rooms	2	-	-	-	0	0	0	20.9	0
Pre-K, East side(1'st floor)	2	-	-	-	0	0	0	20.9	0
Conference room next to Pre-K	2	-	-	-	0	0	0	20.9	0
Open Area "D" North Side	2	-	-	-	0	0	0	20.9	0
Open Area "E" East Side	2	-	-	-	0	0	0	20.9	0
Open Area "F" West Side	2	-	-	-	0	0	0	20.9	0
Open Area "C" East Side	2	-	-	-	0	0	0	20.9	0
Open Area "G" West Side	2	-	-	-	0	0	0	20.9	0
Open Area "H" East Side	2	-	-	-	0	0	0	20.9	0
Library Center	2	-	-	-	0	0	0	20.9	0
Book storage room	2	-	-	-	0	0	0	20.9	0
Teachers Lounge off Library	2	-	-	-	0	0	0	20.9	0
Main Office	2	-	-	-	0	0	0	20.9	0
Open Area "K" West Side	2	-	-	-	0	0	0	20.9	0
Outdoors at South side	2	-	-	-	0	0	0	20.9	0
Room 9	2	-	-	-	0	0	0	20.9	0
Room 8	2	-	-	-	0	0	0	20.9	0
Room 6	2	-	-	-	0	0	0	20.9	0

Custodian closet	2	-	-	-	0	0	0	20.9	0
Nurse Office	2	-	-	-	0	0	0	20.9	0
“I” Area	2	-	-	-	0	0	0	20.9	0
Student Services Conference Room	2	-	-	-	0	0	0	20.9	0
Basement Pre-K area hallway	2	-	-	-	0	0	0	20.9	0
Basement Pre-K Copy area	2	-	-	-	0	0	0	20.9	0
Kitchen next to ovens	2	-	-	-	0	0	0	20.9	0
Kitchen Storage room	2	-	-	-	0	0	0	20.9	0
Kitchen Laundry area	2	-	-	-	0	0	0	20.9	0
Cafeteria, East side	2	-	-	-	0	0	0	20.9	0
Dishwashing room	2	-	-	-	0	0	0	20.9	0
E12 Stairwell	2	-	-	-	0	0	0	20.9	0
Mechanical room (EMR)	2	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Top level class rooms	3	-	-	-	0	0	0	20.9	0
Pre-K, East side(1’st floor)	3	-	-	-	0	0	0	20.9	0
Conference room next to Pre-K	3	-	-	-	0	0	0	20.9	0
Open Area “D” North Side	3	-	-	-	0	0	0	20.9	0
Open Area “E” East Side	3	-	-	-	0	0	0	20.9	0
Open Area “F” West Side	3	-	-	-	0	0	0	20.9	0
Open Area “C” East Side	3	-	-	-	0	0	0	20.9	0
Open Area “G” West Side	3	-	-	-	0	0	0	20.9	0
Open Area “H” East Side	3	-	-	-	0	0	0	20.9	0
Library Center	3	-	-	-	0	0	0	20.9	0
Book storage room	3	-	-	-	0	0	0	20.9	0
Teachers Lounge off Library	3	-	-	-	0	0	0	20.9	0
Main Office	3	-	-	-	0	0	0	20.9	0

Open Area "K" West Side	3	-	-	-	0	0	0	20.9	0
Outdoors at South side	3	-	-	-	0	0	0	20.9	0
Room 9	3	-	-	-	0	0	0	20.9	0
Room 8	3	-	-	-	0	0	0	20.9	0
Room 6	3	-	-	-	0	0	0	20.9	0
Custodian closet	3	-	-	-	0	0	0	20.9	0
Nurse Office	3	-	-	-	0	0	0	20.9	0
"T" Area	3	-	-	-	0	0	0	20.9	0
Student Services Conference Room	3	-	-	-	0	0	0	20.9	0
Basement Pre-K area hallway	3	-	-	-	0	0	0	20.9	0
Basement Pre-K Copy area	3	-	-	-	0	0	0	20.9	0
Kitchen next to ovens	3	-	-	-	0	0	0	20.9	0
Kitchen Storage room	3	-	-	-	0	0	0	20.9	0
Kitchen Laundry area	3	-	-	-	0	0	0	20.9	0
Cafeteria, East side	3	-	-	-	0	0	0	20.9	0
Dishwashing room	3	-	-	-	0	0	0	20.9	0
E12 Stairwell	3	-	-	-	0	0	0	20.9	0
Mechanical room (EMR)	3	-	-	-	0	0	0	20.9	0
Maintenance area, East side	3	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Top level class rooms	4	-	-	-	0	0	0	20.9	0
Pre-K, East side(1'st floor)	4	-	-	-	0	0	0	20.9	0
Conference room next to Pre-K	4	-	-	-	0	0	0	20.9	0
Open Area "D" North Side	4	-	-	-	0	0	0	20.9	0
Open Area "E" East Side	4	-	-	-	0	0	0	20.9	0
Open Area "F" West Side	4	-	-	-	0	0	0	20.9	0
Open Area "C" East Side	4	-	-	-	0	0	0	20.9	0

Open Area "G" West Side	4	-	-	-	0	0	0	20.9	0
Open Area "H" East Side	4	-	-	-	0	0	0	20.9	0
Library Center	4	-	-	-	0	0	0	20.9	0
Book storage room	4	-	-	-	0	0	0	20.9	0
Teachers Lounge off Library	4	-	-	-	0	0	0	20.9	0
Main Office	4	-	-	-	0	0	0	20.9	0
Open Area "K" West Side	4	-	-	-	0	0	0	20.9	0
Outdoors at South side	4	-	-	-	0	0	0	20.9	0
Room 9	4	-	-	-	0	0	0	20.9	0
Room 8	4	-	-	-	0	0	0	20.9	0
Room 6	4	-	-	-	0	0	0	20.9	0
Custodian closet	4	-	-	-	0	0	0	20.9	0
Nurse Office	4	-	-	-	0	0	0	20.9	0
"T" Area	4	-	-	-	0	0	0	20.9	0
Student Services Conference Room	4	-	-	-	0	0	0	20.9	0
Basement Pre-K area hallway	4	-	-	-	0	0	0	20.9	0
Basement Pre-K Copy area	4	-	-	-	0	0	0	20.9	0
Kitchen next to ovens	4	-	-	-	0	0	0	20.9	0
Kitchen Storage room	4	-	-	-	0	0	0	20.9	0
Kitchen Laundry area	4	-	-	-	0	0	0	20.9	0
Cafeteria, East side	4	-	-	-	0	0	0	20.9	0
Dishwashing room	4	-	-	-	0	0	0	20.9	0
E12 Stairwell	4	-	-	-	0	0	0	20.9	0
Mechanical room (EMR)	4	1355	-	-	0	0	0	20.9	0

APPENDIX B

Mold Laboratory Analytical Results