

APPENDIX A

Direct Reading Environmental Measurements from August 4th, 2021

Direct Reading Environmental Measurements – Obtained by a technician on August 4th, 2021 between 1420 and 1557 hours from within Chace Street Elementary School.

LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Outdoors at front	1	1420	-	-	0	0	0	20.9	0
Conference room at front	1	-	-	-	0	0	0	20.9	0
Nurses' office	1	-	-	-	0	0	0	20.9	0
Room 6	1	-	-	-	0	0	0	20.9	0
Room 7	1	-	-	-	0	0	0	20.9	0
Room 8	1	-	-	-	0	0	0	20.9	0
Room 12	1	-	-	-	0	0	0	20.9	0
Room 9	1	-	-	-	0	0	0	20.9	0
Room 11	1	-	-	-	0	0	0	20.9	0
Room 15	1	-	-	-	0	0	0	20.9	0
Room 16	1	-	-	-	0	0	0	20.9	0
GYM	1	-	-	-	0	0	0	20.9	0
Room 19	1	-	-	-	0	0	0	20.9	0
Room 21	1	-	-	-	0	0	0	20.9	0
Library	1	-	-	-	0	0	0	20.9	0
Room 5	1	-	-	-	0	0	0	20.9	0
Room 2	1	-	-	-	0	0	0	20.9	0
Room 24	1	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Outdoors at front	2	-	-	-	0	0	0	20.9	0
Conference room at front	2	-	-	-	0	0	0	20.9	0
Nurses' office	2	-	-	-	0	0	0	20.9	0
Room 6	2	-	-	-	0	0	0	20.9	0
Room 7	2	-	-	-	0	0	0	20.9	0

Room 8	2	-	-	-	0	0	0	20.9	0
Room 12	2	-	-	-	0	0	0	20.9	0
Room 9	2	-	-	-	0	0	0	20.9	0
Room 11	2	-	-	-	0	0	0	20.9	0
Room 15	2	-	-	-	0	0	0	20.9	0
Room 16	2	-	-	-	0	0	0	20.9	0
GYM	2	-	-	-	0	0	0	20.9	0
Room 19	2	-	-	-	0	0	0	20.9	0
Room 21	2	-	-	-	0	0	0	20.9	0
Library	2	-	-	-	0	0	0	20.9	0
Room 5	2	-	-	-	0	0	0	20.9	0
Room 2	2	-	-	-	0	0	0	20.9	0
Room 24	2	-	-	-	0	0	0	20.9	0
LOCATION	TEST Round	Time (EDT)	RH (%)	Temp (Deg F)	H2S (ppm)	LEL (%)	CO (ppm)	O (%)	VOC (ppm)
ACCEPTABLE LIMIT			<60	67 to 82	<20	<10%	<9	19.5 to 23.5	<100
Outdoors at front	3	-	-	-	0	0	0	20.9	0
Conference room at front	3	-	-	-	0	0	0	20.9	0
Nurses' office	3	-	-	-	0	0	0	20.9	0
Room 6	3	-	-	-	0	0	0	20.9	0
Room 7	3	-	-	-	0	0	0	20.9	0
Room 8	3	-	-	-	0	0	0	20.9	0
Room 12	3	-	-	-	0	0	0	20.9	0
Room 9	3	-	-	-	0	0	0	20.9	0
Room 11	3	-	-	-	0	0	0	20.9	0
Room 15	3	-	-	-	0	0	0	20.9	0
Room 16	3	-	-	-	0	0	0	20.9	0
GYM	3	-	-	-	0	0	0	20.9	0
Room 19	3	-	-	-	0	0	0	20.9	0
Room 21	3	-	-	-	0	0	0	20.9	0
Library	3	-	-	-	0	0	0	20.9	0
Room 5	3	-	-	-	0	0	0	20.9	0
Room 2	3	-	-	-	0	0	0	20.9	0
Room 24	3	1557	-	-	0	0	0	20.9	0

APPENDIX B

Mold Laboratory Analytical Results